

### ! CAUTION

- All wiring should be done by a licensed electrician in accordance with state codes, local codes and National Electric Code (NEC) standards or International Electrotechnical Commission (IEC) standards.
- Improper installation may result in serious injury and void warranty.
- Contains parts and assemblies susceptible to damage by electrostatic discharge (ESD).
- When using luminaires, basic safety precautions should always be followed to reduce the risk of fire, electric shock and personal injury.

Included in the Cube-Light Visor Kit: visor and two (2) M4 x 12 mm screws.

### Installation

1. Determine on which side of the lens you would like the visor mounted, keeping in mind the visor can be mounted on any of the four (4) sides.
2. Remove two (2) of the M4 x 10 mm screws securing the lens to the fixture. Discard these screws as they are not long enough to secure the visor to the fixture. Refer to Figure 1.
3. Insert two (2) M4 x 12 mm screws into the visor and then the lens. Refer to Figure 2. Torque to 15 inch-pounds.

Figure 1




Figure 2

